

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	226	(test\$4 evaluat\$5) near4 (fatigue stress strength tough\$3 durab\$4) near4 (specimen material sample workpiece testpiece object).clm.	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:46
2	BRS	L7	93	1 and (clamp\$3 grip\$3 fasten\$4)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:47
3	BRS	L13	42	7 and (sensor probe detector transducer)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:47
4	BRS	L19	28	13 and (vibration oscillation motion)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:48
5	BRS	L25	23	19 and (control\$6)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:49
6	BRS	L26	10	25 and (crack slit fracture)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:49

	Type	L #	Hits	Search Text	DBs	Time Stamp
7	BRS	L32	8	26 and (failure break decay)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:49
8	BRS	L38	6	32 and (frequenc\$3)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:50
9	BRS	L44	6	38 and (load)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:59
10	BRS	L50	3	44 and (spring)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 15:59
11	BRS	L56	3	50 and (actuator)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 16:00
12	BRS	L62	3	56 and (heat\$4)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 16:01

	Type	L #	Hits	Search Text	DBs	Time Stamp
13	BRS	L68	3	62 and (frame housing)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2002/06/28 16:02